

C-A OPERATIONS PROCEDURES MANUAL

8.33.b J10 Power Supply Shut-Down Check Off List

C-A OPM Procedures in which this Attachment is used.		
8.33		

<u>HPC No.</u>	<u>Date</u>	<u>Page Nos.</u>	<u>Initials</u>
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Revision 01
August 13, 2003

J10 Dump Bump Supply SHUT-DOWN Check Off List
--

1. Request the C-A Main Control Room Coordinator to set J10 power supply set-point to zero. []
2. Verify that the AC volts meter is working on the PS. []
3. Verify that the AC line voltage indicator lights are ON. []
4. When the J10 PS is at Zero output current then set Local / Remote switch to Local. []
5. Set PS to Standby. []
6. Set PS to Off. []
7. De-energized 120 VAC control circuit breaker on the J10 PS. []
8. Place AC disconnect switch in the Off position. []
9. Verify that the AC volts meter is de-energized. []
10. De-energized circuit breaker #5 (J10 UPS PLC) on the RF UPS Distribution panel. []
11. Log on the J10 Power Supply Logbook that the SHUT-DOWN procedure has been finished. []

NOTES:

Completed By: _____

Date: _____
